TEXAS DEPARTMENT OF MOTOR VEHICLES CASE NO. 22-0001347 CAF

THOMAS and DIANNE REIFF,	§	BEFORE THE OFFICE
Complainants	§	
-	§	
V.	§	OF
	§	
GENERAL MOTORS LLC,	Ş	
Respondent	§	ADMINISTRATIVE HEARINGS

DECISION AND ORDER

Thomas Reiff, and Dianne Reiff (Complainants) filed a complaint with the Texas Department of Motor Vehicles (Department) seeking relief pursuant to Texas Occupations Code §§ 2301.601-2301.613 (Lemon Law) for alleged warrantable defects in their vehicle manufactured by General Motors LLC (Respondent). A preponderance of the evidence does not show that the subject vehicle continues to have a warrantable defect Consequently, the Complainants' vehicle does not qualify for repurchase/replacement or warranty repair.

I. Procedural History, Notice and Jurisdiction

Matters of notice of hearing¹ and jurisdiction were not contested and are discussed only in the Findings of Fact and Conclusions of Law. The hearing in this case convened on April 20, 2022, in Huntsville, Texas, before Hearings Examiner Andrew Kang, and the record closed on the same day. The Complainants, represented themselves. Kevin Phillips, Business Resource Manager, represented the Respondent.

¹ TeX. GOV'T CODE § 2001.051.

II. Discussion

A. Applicable Law

1. Repurchase/Replacement Relief Requirements

Repurchase and replacement relief only apply to new vehicles.² A vehicle qualifies for repurchase or replacement if the respondent cannot "conform a motor vehicle to an applicable express warranty by repairing or correcting a defect or condition that creates a serious safety hazard or substantially impairs the use or market value of the motor vehicle after a reasonable number of attempts."³ In other words, (1) the vehicle must have a defect covered by an applicable warranty (warrantable defect); (2) the defect must either (a) create a serious safety hazard or (b) substantially impair the use or market value of the vehicle; and (3) the defect must currently exist after a "reasonable number of attempts" at repair.⁴ In addition, the Lemon Law imposes other requirements for repurchase/replacement relief, including (1) a written notice of the defect to the respondent, (2) an opportunity to cure by the respondent, and (3) a deadline for filing a Lemon Law complaint.

a. Serious Safety Hazard

The Lemon Law defines "serious safety hazard" as a life-threatening malfunction or nonconformity that: (1) substantially impedes a person's ability to control or operate a vehicle for ordinary use or intended purposes, or (2) creates a substantial risk of fire or explosion.⁵

b. Substantial Impairment of Use or Value

i. Impairment of Use

The Department applies a reasonable purchaser standard for determining whether a defect substantially impairs use. Under this standard, the factfinder considers "whether a defect or nonconformity hampers the intended normal operation of the vehicle" from the perspective of a reasonable prospective purchaser. For instance, "while a vehicle with a non-functioning air

- ⁴ TEX. OCC. CODE § 2301.604(a).
- ⁵ TEX. OCC. CODE § 2301.601(4).

² TEX. OCC. CODE § 2301.603.

³ TEX. OCC. CODE § 2301.604(a).

conditioner would be available for use and transporting passengers, its intended normal use would be substantially impaired."⁶

ii. Impairment of Value

The Department applies a reasonable purchaser standard for determining whether a defect substantially impairs the value of a vehicle. The reasonable purchaser standard "does not require an owner to present an expert witness or any technical or market-based evidence to show decreased value." Instead, under this standard, "factfinders should put themselves in the position of a reasonable prospective purchaser of the subject vehicle and determine (based on the evidence presented) if the current condition of the vehicle would deter them from buying the vehicle or substantially negatively affect how much they would be willing to pay for the vehicle."⁷

c. Reasonable Number of Repair Attempts

Generally, a rebuttable presumption is established that the vehicle had a reasonable number of repair attempts if:

[T]he same nonconformity continues to exist after being subject to repair four or more times by the manufacturer, converter, or distributor or an authorized agent or franchised dealer of a manufacturer, converter, or distributor and the attempts were made before the earlier of: (A) the date the express warranty expires; or (B) 24 months or 24,000 miles, whichever occurs first, following the date of original delivery of the motor vehicle to the owner.⁸

Alternatively, for serious safety hazards, a rebuttable presumption is established that the vehicle had a reasonable number of repair attempts if:

[T]he same nonconformity creates a serious safety hazard and continues to exist after causing the vehicle to have been subject to repair two or more times by the manufacturer, converter, or distributor or an authorized agent or franchised dealer of a manufacturer, converter, or distributor and the attempts were made before the earlier of: (A) the date the express warranty expires; or (B) 24 months or 24,000

⁶ Dutchmen Manufacturing, Inc. v. Texas Department of Transportation, Motor Vehicle Division, 383 S.W.3d 217, 228 (Tex. App.—Austin 2012).

⁷ Dutchmen Manufacturing, Inc. v. Texas Department of Transportation, Motor Vehicle Division, 383 S.W.3d 217, 228 (Tex. App.—Austin 2012) ("We find that this interpretation of the standard required for demonstrating substantial impairment is reasonable and consistent with the statute's plain language which requires a showing of loss in market value. . . . [T]he Division's interpretation that expert testimony or technical or market-based evidence is not required to show diminished value or use is consistent with the statute's goal of mitigating manufacturers' economic advantages in warranty-related disputes.").

⁸ TEX. OCC. CODE § 2301.605(a)(1)(A) and (B).

miles, whichever occurs first, following the date of original delivery of the motor vehicle to the owner.⁹

Additionally, for vehicles out of service at least 30 days, a rebuttable presumption may be established that the vehicle had a reasonable number of repair attempts if:

[A] nonconformity still exists that substantially impairs the vehicle's use or market value, the vehicle is out of service for repair for a cumulative total of 30 or more days, and the attempts were made before the earlier of: (A) the date the express warranty expires; or (B) 24 months or 24,000 miles, whichever occurs first, following the date of original delivery of the motor vehicle to the owner.¹⁰

The 30 days described above does not include any period when the owner has a comparable loaner vehicle provided while the dealer repairs the subject vehicle.¹¹

The existence of a statutory rebuttable presumption does not preclude otherwise finding a reasonable number of attempts to repair the vehicle based on different circumstances and fewer attempts.¹² Furthermore, the Department adopted a decision indicating that if a consumer presents the vehicle to a dealer for repair and the dealer fails to repair the vehicle, then that visit would constitute a repair attempt unless the consumer was at fault for the failure to repair the vehicle.¹³

d. Other Requirements

Even if a vehicle satisfies the preceding requirements for repurchase/replacement relief, the Lemon Law prohibits repurchase or replacement unless: (1) the owner or someone on behalf of the owner, or the Department has provided written notice of the alleged defect or nonconformity to the respondent;¹⁴ (2) the respondent was given an opportunity to cure the defect or

¹³ DaimlerChrysler Corporation v. Williams, No. 03-99-00822-CV (Tex. App.—Austin, June 22, 2000, no writ) (not designated for publication) (Repair attempts include "those occasions when the fault for failing to repair the vehicle rests with the dealership." Conversely, "those occasions when failure to repair the vehicle was the fault of the consumer would not be considered a repair attempt under the statute.").

¹⁴ 43 TEX. ADMIN. CODE § 215.204 provides that "[u]pon receipt of a complaint for lemon law or warranty performance relief, the department will provide notification of the complaint to the appropriate manufacturer, converter, or distributor." The Department's notice of the complaint to the Respondent satisfies the requirement to provide notice of the defect or nonconformity to the Respondent. TEX. OCC. CODE § 2301.606(c)(1).

⁹ TEX. OCC. CODE § 2301.605(a)(2).

¹⁰ TEX. OCC. CODE § 2301.605(a)(3).

¹¹ TEX. OCC. CODE § 2301.605(c).

¹² Ford Motor Company v. Texas Department of Transportation, 936 S.W.2d 427, 432 (Tex. App.—Austin 1996, no writ) ("[T]he existence of statutory presumptions does not forbid the agency from finding that different circumstances or fewer attempts meet the requisite 'reasonable number of attempts."").

nonconformity;¹⁵ and (3) the Lemon Law complaint was filed within six months after the earliest of: the warranty's expiration date or the dates on which 24 months or 24,000 miles had passed since the date of original delivery of the motor vehicle to an owner.¹⁶

2. Warranty Repair Relief

If repurchase or replacement relief does not apply, a vehicle may still qualify for warranty repair if the vehicle has a "defect . . . that is covered by a manufacturer's, converter's, or distributor's . . . warranty agreement applicable to the vehicle"; the vehicle owner provided written notice of the defect to the manufacturer, converter, distributor, or its authorized agent before the warranty's expiration; and the owner filed a complaint with the Department specifying the defect.¹⁷ The manufacturer, converter, or distributor has an obligation to "make repairs necessary to conform a new motor vehicle to an applicable . . . express warranty."¹⁸

3. Burden of Proof

The law places the burden of proof on the Complainants.¹⁹ The Complainants must prove <u>all facts</u> required for relief by a preponderance of the evidence. That is, the Complainants must present sufficient evidence to show that <u>every required fact</u> more likely than not exists.²⁰ Accordingly, the Complainants cannot prevail where the existence of any required fact appears unlikely or appears equally likely or unlikely.

¹⁵ TEX. OCC. CODE § 2301.606(c)(2). A respondent may delegate its opportunity to cure to a dealer. A repair visit to a dealer may satisfy the opportunity to cure requirement when the respondent authorizes a dealer to attempt repair after written notice to the respondent. *Dutchmen Manufacturing, Inc. v. Texas Department of Transportation, Motor Vehicle Division*, 383 S.W.3d 217, 221 and 226 (Tex. App.—Austin 2012); Texas Department of Transportation, *Kennemer v. Dutchman Manufacturing, Inc.*, MVD Cause No. 09-0091 CAF (Motor Vehicle Division Sept. 25, 2009) (Final Order Granting Chapter 2301, Subchapter M Relief). An opportunity to cure does not require an actual repair attempt but only a valid opportunity. *Id* at 2. A respondent forgoes its opportunity to repair by replying to a written notice of defect with a settlement offer instead of arranging a repair attempt. *Id* at 2.

¹⁶ TEX. OCC. CODE § 2301.606(d)(2).

¹⁷ TEX. OCC. CODE § 2301.204; 43 TEX. ADMIN. CODE § 215.202(b)(3).

¹⁸ TEX. OCC. CODE § 2301.603(a).

¹⁹ 43 TEX. ADMIN. CODE § 215.66(d); *see Vance v. My Apartment Steak House, Inc.*, 677 S.W.2d 480, 482 (Tex. 1984) ("[A] civil litigant who asserts an affirmative claim for relief has the burden to persuade the finder of fact of the existence of each element of his cause of action.").

²⁰ E.g., Southwestern Bell Telephone Company v. Garza, 164 S.W.3d 607, 621 (Tex. 2005).

4. The Complaint Identifies the Relevant Issues in this Case

The complaint identifies the relevant issues to address in this case.²¹ The complaint must state "sufficient facts to enable the department and the party complained against to know the nature of the complaint and the specific problems or circumstances forming the basis of the claim for relief under the lemon law."²² However, the parties may expressly or impliedly consent to hearing issues not included in the pleadings.²³ Implied consent occurs when a party introduces evidence on an unpleaded issue without objection.²⁴ Because the complaint determines the relevant issues, the Department cannot order relief for an issue not included in the complaint unless tried by consent.²⁵

5. Incidental Expenses

When repurchase or replacement is ordered, the Lemon Law provides for reimbursing the Complainants for reasonable incidental expenses resulting from the vehicle's loss of use because of the defect.²⁶ Reimbursable expenses include, but are not limited to: (1) alternate transportation; (2) towing; (3) telephone calls or mail charges directly attributable to contacting the manufacturer, distributor, converter, or dealer regarding the vehicle; (4) meals and lodging necessitated by the vehicle's failure during out-of-town trips; (5) loss or damage to personal property; (6) attorney fees, if the complainant retains counsel <u>after</u> notification that the respondent is represented by counsel; and (7) items or accessories added to the vehicle at or after purchase, less a reasonable allowance for use. The expenses must be reasonable and verifiable (for example, through receipts

²¹ "In a contested case, each party is entitled to an opportunity: (1) for hearing after reasonable notice of not less than 10 days; and (2) to respond and to present evidence and argument on each issue involved in the case." TEX. GOV'T CODE § 2001.051; "Notice of a hearing in a contested case must include . . . either: (A) a short, plain statement of the factual matters asserted; or (B) an attachment that incorporates by reference the factual matters asserted in the complaint or petition filed with the state agency." TEX. GOV'T CODE § 2001.052. *See* TEX. OCC. CODE § 2301.204(b) ("The complaint must be made in writing to the applicable dealer, manufacturer, converter, or distributor and must specify each defect in the vehicle that is covered by the warranty."); TEX. OCC. CODE § 2301.204(d) ("A hearing may be scheduled on any complaint made under this section that is not privately resolved between the owner and the dealer, manufacturer, converter, or distributor.").

²² 43 TEX. ADMIN. CODE § 215.202(a)(3).

²³ 43 Tex. Admin. Code § 215.42; Tex. R. Civ. P. 67.

²⁴ See Gadd v. Lynch, 258 S.W.2d 168, 169 (Tex. Civ. App.—San Antonio 1953, writ ref'd).

²⁵ See TEX. GOV'T CODE §§ 2001.141(b)-(c), 2001.051-2001.052; TEX. R. CIV. P. 301.

²⁶ TEX. OCC. CODE § 2301.604.

or similar written documents).²⁷ However, the Department's rules expressly exclude compensation for "any interest, finance charge, or insurance premiums."²⁸

B. Summary of Complainants' Evidence and Arguments

On December 19, 2020, the Complainants, purchased a new 2021 GMC Sierra 1500 from Wiesner of Huntsville, a franchised dealer of the Respondent, in Huntsville, Texas. The Complainants took delivery of the vehicle on December 19, 2020. The vehicle had nine (9) miles on the odometer at the time of purchase. The vehicle's limited warranty provides bumper to bumper coverage for three years or 36,000 miles, whichever occurs first, and powertrain coverage for five years or 60,000 miles, whichever occurs first.

On or about October 4, 2021, the Complainants sent a written notice of defect to the Respondent. However, the Respondent did not receive such notice. On October 4, 2021, the Complainants filed a complaint with the Department alleging that the transmission will not work and vibration causes the engine to stop. On or about October 4, 2021, the Department provided notice of the complaint to the Respondent.

In relevant part, the Complainants took the vehicle to a dealer for repair of the alleged issues as follows:

Date	Miles	Issue
08/05/21	19,956	Service engine soon light – loss of communication code
		Truck died while driving, service engine soon light – transmission
08/26/21	20,813	valve stuck
		Service engine soon light – NOx sensor exceeded learning limits,
		weak and broken circuits at connector on EGR valve differential
03/01/22	30,281	pressure sensor
		Check engine light – NOx sensor exceeded minimum learning limit,
		NOx catalyst efficiency below threshold, NOx sensor 3 105 ppm
03/07/22	30,985	greater than NOx sensor 1

Mr. Reiff testified that the subject vehicle died leaving Huntsville and on the way to the dealer, where he left the vehicle for two months. The dealer did not provide a loaner vehicle. Mr. Reiff contended that the two later instances of the check engine light related to the issues in

²⁷ 43 Tex. Admin. Code § 215.209(a).

²⁸ 43 TEX. ADMIN. CODE § 215.208(b)(1).

this case. He noted that he received an e-mail from OnStar regarding the need for transmission service. He described the vibration as more severe than an out of balance tire, which lessened after 30 mph but was still noticeable. The transmission was replaced but the service engine light came on. Mr. Reiff affirmed that the transmission and vibration issues appear related, noting that he received an OnStar notice and the check engine light came on. He stated the transmission issue occurred two or four times. He believed the diagnostic trouble codes related to the transmission issue, though he did not know the origin of the codes. Mr. Reiff did not notice the transmission issue after the last repair but added that the issue appeared to occur in a 90-day pattern. Mr. Reiff described that the vibration issue occurred when pressing the accelerator at a stop, causing the vehicle to vibrate violently. He elaborated that had to ease into the accelerator to keep the vehicle running, almost like a manual clutch. He confirmed this occurred on August 4th and 26th (of 2021). He affirmed that this engine stoppage last occurred in August of 2021.

On cross-examination, Mr. Reiff testified that he had not seen the service engine light since the last repair visit. Likewise, he acknowledged that the engine has not stopped since the last repair visit and that the complained of vibration did not occur during the test drive.

C. Inspection

Upon inspection at the hearing, the vehicle's odometer displayed 32,700 miles. No warning lights were illuminated. The vehicle was test driven primarily on service roads, a freeway, and local roads. The test drive ended with 32,712 miles on the odometer. No warning lights were illuminated at the end of the test drive. The vehicle appeared to operate normally. Inspection of the exterior revealed a small dent on the rear passenger door.

D. Summary of Respondent's Evidence and Arguments

Bruce Morris, Field Service Engineer, testified that the vehicle had excessive debris in the transmission pan and the fluid pump idler gear bearing was missing. The metal debris ran through the transmission, requiring a rebuild or replacement of the transmission. Accordingly, the transmission and torque converters were replaced. Mr. Morris elaborated that this transmission issue could stop a gear and cause a stall. Mr. Morris explained that a service engine soon light may arise from about 500 conditions, which may relate to the engine, emissions, or brakes. The codes must be inspected for the specific issue. Two repairs orders regarding the service engine soon light

concerned a NOx sensor wire and a NOx sensor was replaced in March 2022. Mr. Morris stated that the last repair order related to an emissions issue (not a complaint issue). Mr. Morris affirmed gas engines normally vibrate and diesel engines vibrate more powerfully. He elaborated that serious vibration would have occurred at failure, not during normal operation.

On cross-examination, Mr. Morris confirmed that an inspection was not arranged with Mr. Reiff. Rather, the vehicle had already been inspected. He explained that the transmission issue in the bulletin applied to all 10 speed transmission idler gears. He added that most likely, the vehicle's bearings were coming apart at the first repair visit and completely gone by the second.

Mr. Phillips testified that the Respondent never received notice from the customer and only one of the repair orders related to the complaint concerns.

E. Analysis

The record shows that the vehicle had a substantial defect. However, as explained in the discussion of applicable law, to qualify for relief, a preponderance of the evidence must show that the defect continues to exist after repairs. In this case, the available evidence reflects that the transmission and vibration issues did not reoccur after the last repair visit on March 7, 2022. Consequently, the subject vehicle does not qualify for relief.

III. Findings of Fact

- On December 19, 2020, the Complainants, purchased a new 2021 GMC Sierra 1500 from Wiesner of Huntsville, a franchised dealer of the Respondent, in Huntsville, Texas. The vehicle had nine (9) miles on the odometer at the time of purchase.
- On December 19, 2020, the Complainants, purchased a new 2021 GMC Sierra 1500 from Wiesner of Huntsville, a franchised dealer of the Respondent, in Huntsville, Texas. The Complainants took delivery of the vehicle on December 19, 2020. The vehicle had nine miles on the odometer at the time of purchase.
- 3. The Complainants took the vehicle to a dealer for repair as shown below:

Date	Miles	Issue
08/05/21	19,956	Service engine soon light – loss of communication code
		Truck died while driving, service engine soon light – transmission
08/26/21	20,813	valve stuck
		Service engine soon light – NOx sensor exceeded learning limits,
		weak and broken circuits at connector on EGR valve differential
03/01/22	30,281	pressure sensor
		Check engine light – NOx sensor exceeded minimum learning limit,
		NOx catalyst efficiency below threshold, NOx sensor 3 105 ppm
03/07/22	30,985	greater than NOx sensor 1

- 4. On or about October 4, 2021, the Complainants sent a written notice of defect to the Respondent. However, the Respondent did not receive such notice.
- On October 4, 2021, the Complainants filed a complaint with the Department alleging that the transmission will not work and vibration causes the engine to stop. On or about October 4, 2021, the Department provided notice of the complaint to the Respondent.
- 6. On January 13, 2022, the Department's Office of Administrative Hearings issued a notice of hearing directed to all parties, giving them not less than 10 days' notice of hearing and their rights under the applicable rules and statutes. The notice stated the time, place and nature of the hearing; the legal authority and jurisdiction under which the hearing was to be held; particular sections of the statutes and rules involved; and the factual matters asserted.
- 7. The hearing in this case convened on April 20, 2022, in Huntsville, Texas, before Hearings Examiner Andrew Kang, and the record closed on the same day. The Complainants, represented themselves. Kevin Phillips, Business Resource Manager, represented the Respondent.
- 8. The vehicle's odometer displayed 32,700 miles at the time of the hearing.
- 9. The vehicle's warranty was in effect at the time of the hearing.
- 10. The vehicle operated normally during the test drive at the hearing.
- 11. The alleged defects did not continue to exist after repairs.

IV. Conclusions of Law

- The Texas Department of Motor Vehicles has jurisdiction over this matter. TEX. OCC. CODE §§ 2301.601-2301.613 and 2301.204.
- 2. A hearings examiner of the Department's Office of Administrative Hearings has jurisdiction over all matters related to conducting a hearing in this proceeding, including the preparation of a decision with findings of fact and conclusions of law, and the issuance of a final order. TEX. OCC. CODE § 2301.704.
- The Complainants filed a sufficient complaint with the Department. 43 TEX. ADMIN. CODE § 215.202.
- The parties received proper notice of the hearing. TEX. GOV'T CODE §§ 2001.051, 2001.052. 43 TEX. ADMIN. CODE § 215.206(2).
- 5. The Complainants bears the burden of proof in this matter. 43 TEX. ADMIN. CODE § 206.66(d).
- 6. The Complainants' vehicle does not qualify for replacement or repurchase. The Complainants did not prove that the vehicle has a defect covered by the Respondent's warranty. TEX. OCC. CODE §§ 2301.603 and 2301.604(a).
- 7. The Complainants' vehicle does not qualify for replacement or repurchase. The vehicle did not have a reasonable number of repair attempts. TEX. OCC. CODE §§ 2301.604(a) and 2301.605(a).
- Reimbursement of incidental expenses does not apply because the vehicle does not qualify for replacement or repurchase. TEX. OCC. CODE §§ 2301.603, 2301.604(a); 43 TEX. ADMIN. CODE § 215.209.
- 9. The Complainants' vehicle does not qualify for warranty repair. The Complainants did not prove that the vehicle has a defect covered by the Respondent's warranty. TEX. OCC. CODE §§ 2301.204 and 2301.603.
- 10. The Respondent remains responsible to address and repair or correct any defects that are covered by the Respondent's warranty. TEX. OCC. CODE § 2301.603.

V. Order

Based on the foregoing Findings of Fact and Conclusions of Law, it is **ORDERED** that the Complainants' petition for relief pursuant to Texas Occupations Code §§ 2301.601-2301.613 is **DISMISSED**.

SIGNED June 20, 2022

ANDREW KANG HEARINGS EXAMINER OFFICE OF ADMINISTRATIVE HEARINGS TEXAS DEPARTMENT OF MOTOR VEHICLES